

PIERCE MANUFACTURING INC.



BULLETIN

TO: Service Bulletin Distribution

FROM: Joe Barry

DATE: April 2, 2010

RE: Fire Hose Safety Restraints

SERVICE BULLETIN #298



NFPA standards were amended in 2005 to require that all hose storage areas on new apparatus bid after November 2005 include hose restraints.

We believe it is advisable to encourage Pierce apparatus owners to incorporate a hose restraint on all pre-2005 model year apparatus. This feature is a relatively simple measure that will enhance the safety of the apparatus.

Please share this bulletin with your customers.